

Modernisierung/Instandsetzung Wohnhaus

Gottschedstr. 3, Berlin





```
(function() { var sliderElement =
[.slice.call(document.getElementsByClassName('mod_rocksolid_slider'), -1 )][0]; if (window.jQuery &&
jQuery.fn.rstSlider) { init(); } else { document.addEventListener('DOMContentLoaded', init); } function
init() { var $ = jQuery; var slider = $(sliderElement); slider.find('video[data-rsts-background], [data-rsts-
type=video] video').each(function() { // Disable mejs for videos this.player = false; }); slider.rstSlider({ "ty
pe": "slide", "direction": "x", "navType": "thumbs", "scaleMode": "none", "imagePosition": "top-left", "centerCo
ntent": false, "random": false, "loop": false, "videoAutoplay": false, "autoplayProgress": false, "pauseAutoplayOn
Hover": true, "keyboard": true, "captions": false, "controls": true, "thumbControls": true, "combineNavItems": tru
e, "visibleAreaAlign": 0.5, "gapSize": "0%", "thumbs": { "width": "240", "height": "460", "controls": true, "slideMa
xCount": 1, "slideMinSize": 180, "slideMaxSize": 180, "rowMaxCount": 3, "rowMinSize": 180, "prevNextSteps":
```

```
1,"gapSize":20,"direction":"y"})); // Fix missing lightbox links $(function() { if (!$.fn.colorbox) { return;  
} var lightboxConfig = { loop: false, rel: function() { return $(this).attr('data-lightbox'); }, maxWidth:  
'95%', maxHeight: '95%' }; var update = function(links) { links.colorbox(lightboxConfig); }; slider.on('rsts-  
slidestart rsts-slidestop', function(event) { update(slider.find('a[data-lightbox]')); });  
update(slider.find('a[data-lightbox]')); }); } }());
```





```
(function() { var sliderElement =
[].slice.call(document.getElementsByClassName('mod_rocksolid_slider'), -1 )[0]; if (window.jQuery &&
jQuery.fn.rstSlider) { init(); } else { document.addEventListener('DOMContentLoaded', init); } function
init() { var $ = jQuery; var slider = $(sliderElement); slider.find('video[data-rsts-background], [data-rsts-
type=video] video').each(function() { // Disable mejs for videos this.player = false; }); slider.rstSlider({ "ty
pe":"slide", "direction":"x", "navType":"thumbs", "scaleMode":"none", "imagePosition":"top-left", "centerCo
ntent":false, "random":false, "loop":false, "videoAutoplay":false, "autoplayProgress":false, "pauseAutoplayOn
Hover":true, "keyboard":true, "captions":false, "controls":true, "thumbControls":true, "combineNavItems":tru
e, "visibleAreaAlign":0.5, "gapSize":"0%", "thumbs":{"width":"240", "height":"460", "controls":true, "slideMa
xCount":1, "slideMinSize":180, "slideMaxSize":180, "rowMaxCount":3, "rowMinSize":180, "prevNextSteps":
1, "gapSize":20, "direction":"y" } }); // Fix missing lightbox links $(function() { if (!$.fn.colorbox) { return;
} var lightboxConfig = { loop: false, rel: function() { return $(this).attr('data-lightbox'); }, maxWidth:
'95%', maxHeight: '95%' }; var update = function(links) { links.colorbox(lightboxConfig); }; slider.on('rsts-
slidestart rsts-slidestop', function(event) { update(slider.find('a[data-lightbox]')); });
update(slider.find('a[data-lightbox]')); }); } })();
```

Leistungen

- Gebäudeplanung/Architektur

Zeitraum:	2016 - 2017
Anzahl WE/GE:	17/2
Bauherr:	GESOBAU AG

Maßnahmen

- Hüllensanierung
- Balkonanbau
- Freianlagen